



**EMSL Analytical, Inc.**  
 107 Haddon Ave., Westmont, NJ 08108

Phone: (856) 858-4300 Fax: (856) 858-4960 Email: [westmontaslab@EMSL.com](mailto:westmontaslab@EMSL.com)

Attn: **Joel A. Harris**  
**O'Reilly, Talbot & Okun Associates, Inc.**  
 293 Bridge Street  
 Suite 500  
 Springfield, MA 01103

Customer ID: ENVI07  
 Customer PO:  
 Received: 10/18/06 9:30 AM  
 EMSL Order: 040622124

Fax: (413) 786-8830 Phone: (413) 786-6222  
 Project: 160 FRANKLIN ST. WESTFIELD

EMSL Proj:  
 Analysis Date: 10/19/2006  
 Report Date: 10/19/2006

**Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
WP01 SKIM 040622124-0001	WALL	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
WP01 ROUGH 040622124-0001A	WALL	Gray Non-Fibrous Heterogeneous	20% Hair	80% Non-fibrous (other)	None Detected
WP02 SKIM 040622124-0002	WALL	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
WP02 ROUGH 040622124-0002A	WALL	Gray Non-Fibrous Heterogeneous	25% Hair	75% Non-fibrous (other)	None Detected
CP01 040622124-0003	CEILING PANEL	Gray/White Fibrous Heterogeneous	45% Cellulose 30% Min. Wood	25% Non-fibrous (other)	None Detected

Analyst(s)

Erica Valent (5)

Stephen Siegel, CIH  
 or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as < 1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. The test results contained within this report meet the requirements of NELAC unless otherwise noted. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Westmont (NVLAP #101048-0), NY ELAP 10872



EMSL Analytical, Inc.

Asbestos

CHAIN OF CUSTODY

EMSL Representative: Stephen Siegel

Your Company Name: O'Reilly, Talbot & Okun, Assoc.

Street: 693 Bridge St., Suite 500

Box #: \_\_\_\_\_

City/State: Springfield, MA Zip 01103

EMSL-Bill to: \_\_\_\_\_

Street: \_\_\_\_\_

Box #: \_\_\_\_\_

City/State: \_\_\_\_\_ Zip: \_\_\_\_\_

Phone Results to: Name \_\_\_\_\_ Telephone #: \_\_\_\_\_

Fax Results to: Name Joel Harris Fax Number: 413-788-8830

Project Name/Number: 160 Franklin St., Westfield  
J960-06-01

Purchase Order #: \_\_\_\_\_

MATRIX

TURNAROUND

- Air
- Bulk
- Wipe
- Floor Tile
- Drinking Water
- Wastewater
- Soil
- Dust

- 6-10 Days
  - 5 Days
  - 72 Hours
  - 48 Hours
  - 24 Hour
  - 12 Hour
  - Same Day\*
  - 6 Hours
- \*S.D. - A.M. delivery by Fed. Ex. - Results by Mid-night or earlier

- PCM**
- NIOSH 7400
  - OSHA
  - Other: \_\_\_\_\_

- TEM AIR**
- AHERA
  - NIOSH 7402
  - Level I
  - Level II

- TEM WATER**
- Wastewater
  - Drinking Water EPA 100.2
  - Water - NY Wastewater
  - Water-NY Drinking Water

- PLM**
- EPA 600
  - NOB
  - Point Count
  - Other: \_\_\_\_\_

- TEM BULK**
- Drop Mount (Qualitative)
  - Chatfield
  - Chatfield / SEM QC
  - Conventional (Quantitative)
  - EMSL Method
  - NOB
  - NOB / SEM QC
  - Micro Vac - Quantitative
  - Micro Vac - Qualitative

- TEM WIPE**
- Quantitative
  - Qualitative

- EM**
- Qualitative
  - Quantitative

- XRD**
- Asbestos
  - Silica

- OTHER**
- \_\_\_\_\_

Client Sample # (s) \_\_\_\_\_ Total Samples: 3

Relinquished: Harris Date: 10/17/06 Time: 2pm

Received: \_\_\_\_\_ Date: \_\_\_\_\_ Time: \_\_\_\_\_

Received: \_\_\_\_\_ Date: \_\_\_\_\_ Time: \_\_\_\_\_

NOTE: For Additional Samples Use Reverse Side. Please duplicate this form and use additional sheets if necessary.

